Name Of Work: Maintanance of Borewell in Ward No 14,
Bagalagunte T Dasarahalli Sub Div

Est.Cost:10.00 Lakhs

Head Of A/C P.1802

Water Suppy New area's

Job Code No. 014-14-000002

AA No -JC/DZ/105/13-14, D.19.07.2013

TS No-EE/DD/47-13-14, D.31.07.2013

Work Order No. EE/DD/09/14-15, D.05.05.2014

BR NO.769, D.30.12.2014

Inspection date : 10.7.2015

the work spot is inspected by me along with concerned Engineers and ascertained that the work carried out as per the requirements to the site conditions as shown in the photos and physical status of the premises.

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬೆಂಗಳೂರು